



Property Risk Consulting Guidelines

A Publication of AXA XL Risk Consulting

PRC.2.2.3

TESTING OF FIRE DOORS, DAMPERS AND WINDOWS

INTRODUCTION

Fire walls are the last line of defense in a fire. They can prevent a small fire from becoming a major loss. Ideally the best fire wall is one that does not have openings. However, openings are needed to allow materials, equipment and product to pass through. Unfortunately, the presence of any opening in a fire wall increases the likelihood of the spread of a fire into the adjacent area. The fire wall is only as good as the equipment used to protect the openings. If a door, damper or window fails to operate, the investment in the fire wall was for naught.

Loss experience has shown that fire doors fail to fully close at an alarming rate. The reasons for the failures include bent guide rails; stock or material blocking the opening; missing binders and stay rollers; bent shrouds; fusible links missing and the detection system not operating. To make sure these doors can operate properly during fire conditions test and maintain the doors. NFPA 80, Chapter 5 covers care and maintenance of fire doors. Failures of fire dampers range from improper installation to misalignment. Test and maintain fire dampers in accordance with NFPA 80. NFPA 80 states the fire doors shall be tested not less than annually, but leaves the frequency up to the property management, and that fire dampers shall be tested every 4 yr except those in hospitals which shall be tested every 6 yr.

It is better to find out if a fire door or damper would not close during a routine inspection and have the opportunity to repair it, then during a fire when the entire facility could be lost.

POSITION

Visually inspect all fire doors, dampers and windows on a weekly basis. This inspection covers:

- Making sure stock or material does not block the door.
- Combustible material is kept away from the door, damper and window.
- Door, damper and window are in good condition.
- Fusible link is in the proper location or the detector is properly located and functioning.
- For sliding doors including incline and horizontal sliding, check:
 - Roller and tightening wedge are in good condition.
 - Binder (retaining clip) is not bent.
 - Cable to the counterweight (should not use rope) is free to move.

100 Constitution Plaza, Hartford, Connecticut 06103

Copyright® 2020, AXA XL Risk Consulting

Global Asset Protection Services, LLC, AXA Matrix Risk Consultants S.A. and their affiliates ("AXA XL Risk Consulting") provide loss prevention and risk assessment reports and other risk consulting services, as requested. In this respect, our property loss prevention publications, services, and surveys do not address life safety or third party liability issues. This document shall not be construed as indicating the existence or availability under any policy of coverage for any particular type of loss or damage. The provision of any service does not imply that every possible hazard has been identified at a facility or that no other hazards exist. AXA XL Risk Consulting does not assume, and shall have no liability for the control, correction, continuation or modification of any existing conditions or operations. We specifically disclaim any warranty or representation that compliance with any advice or recommendation in any document or other communication will make a facility or operation safe or healthful, or put it in compliance with any standard, code, law, rule or regulation. Save where expressly agreed in writing, AXA XL Risk Consulting and its related and affiliated companies disclaim all liability for loss or damage suffered by any party arising out of or in connection with our services, including indirect or consequential loss or damage, howsoever arising. Any party who chooses to rely in any way on the contents of this document does so at their own risk.

- For swinging doors, check:
 - Closing mechanism (counterweights or closure) is in good condition.
 - Door latches operate.
 - Swing path is free of material.
- For roll-up doors, check:
 - Closing mechanism (counter weights or closure).
 - Door rails are not bent.
 - Condition of shroud above opening.

Completely shut all the fire doors, dampers and windows on a monthly basis. If the closure is detector activated, operate detector. Make sure the door, damper or window closes fully and tightly.

If the door is fusible-link activated, annually close the door by removing the link.

Inspect conveyor openings (door closing device included) in addition to the above, check how the conveyor is shut off and location of material on the conveyor when it stops.

Correct any deficiencies or problems as they are discovered. Keep all doors or shutters closed that do not fully close automatically.